

Summary of Facility Information in the County of Park

Owner Name and Address: Dale Jones PO Box 90 Clyde Park MT 59018 Phone: (406) 686-4681

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3407600	Dales Conoco	301 1st Ave	Clyde Park	59018	(406) 686-4681

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
5 / 05 Currently In Use	3991	4/1/1999 07 / No	Gasoline 6,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																						
6 / 06 Currently In Use	3992	4/1/1999 07 / No	Gasoline 2,500	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																						
7 / 07 Currently In Use	3993	4/1/1999 07 / No	Diesel 1,900	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																						
8 / 08 Currently In Use	3994	4/1/1999 07 / No	Diesel 1,900	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Shields Valley School Dist PO Box 131 Wilsall MT 59086 Phone: (406) 578-2176

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3412515	Shields Valley High School	401 1st St E	Clyde Park	59018	(406) 686-4621

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently in Use	2725	7/1/1965 41 / No	Diesel 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Rick D Sommers PO Box 1128 Cooke City MT 59020 Phone: (406) 838-2244

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3401584	Cooke City Exxon	US Highway 212	Cooke City	59020	(406) 838-2244

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
7 / 07 Currently in Use	757	10/1/1991 14 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
8 / 08 Currently in Use	758	10/1/1991 14 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
9 / 09 Currently In Use	759	10/1/1997 08 / No	Diesel 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
10 / 10 Currently In Use	760	10/1/1997 08 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Montana Abundance LLP 315 Emerald Hills Dr Billings MT 59101 Phone: (406) 252-1777

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3402162	Soda Butte Lodge	209 US Highway 212	Cooke City	59020	(406) 838-2251

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / S5 Currently in Use	3383	5/1/1996 10 / No	Heating Oil 4,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Yellowstone Park Service Station PO Box 168 Yellowstone Natl Park WY 82190 Phone: (307) 344-2333

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3408869	Northeast Entrance Gas Pumps		Cooke City	59020	

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 04 Currently in Use	1741	8/1/1992 13 / No	Gasoline 2,000	Cathodically Protected Steel Double-Walled	Galvanized Steel Double-Walled/Non-Corro	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>	No Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>																					
2 / 05 Currently in Use	1742	8/1/1992 13 / No	Diesel 2,000	Cathodically Protected Steel Double-Walled	Galvanized Steel Double-Walled/Non-Corro	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>	No Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Cooke City Sinclair & Cabins PO Box 1030 Cooke City MT 59020 Phone: (406) 838-2000

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3410046	Cooke City Sinclair and Cabins	115 Main St	Cooke City	59020	(406) 838-2000

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
6 / 06 Currently In Use	3670	10/1/1998 07 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
7 / 07 Currently In Use	3671	10/1/1998 07 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Yellowstone Park Service Station PO Box 168 Yellowstone Natl Park WY 82190 Phone: (307) 344-2333

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3410927	Northeast Entrance Bldg 251		Cooke City	59020	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / S2 Currently in Use	1743	8/1/1992 13 / No	Heating Oil 560	STI-P3 Double-Walled	Copper Double-Walled/Non-Corro	U.S. Suction	<div style="display: flex; justify-content: space-between; padding: 2px;"> (A) (B) (C) (D) (E) (F) (●) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B) (D) (E) (F) (●) (H) (I) (J) (K) (L) </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Bert Otis 3 Murphy Ln PO Box 60 Emigrant MT 59027 Phone: (406) 333-4434

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3406713	Emigrant General Store	3 Murphy Ln	Emigrant	59027	(406) 333-4434

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 02 Currently in Use	4351	9/1/1989 16 / No	Gasoline 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
5 / 06 Currently in Use	4352	1/1/1997 09 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
6 / 01 Currently in Use	4353	9/1/1989 16 / No	Diesel 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Community Continuity Inc 8900 Bradford Pl PO Box 539 Emigrant MT 59027 Phone: (406) 333-4727

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3410930	Community Continuity Inc	18 Polaris Way Parcel 70 S Glastonbury	Emigrant	59027	(406) 333-4727

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently in Use	4821	2/1/1990 16 / No	Diesel 20,000	STI-P3 None	Flexible Plastic Double-Walled	Gravity Feed	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Community Restoration Inc PO Box 414 Emigrant MT 59027 Phone: (800) 631-8885

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3410931	Community Restoration Inc	Hercules Road & Polaris Way	Emigrant	59027	(800) 631-8885

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently in Use	701	2/20/1990 16 / No	Diesel 20,000	STI-P3 None	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Shelter Invincible Inc PO Box 39 Emigrant MT 59027 Phone: (406) 333-4485

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3410933	Shelter Invincible Inc	25 Gemini Road	Emigrant	59027	(406) 333-4485

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
Status									Spill/Overl/C
1 / 01 Currently in Use	1882	4/17/1990 16 / No	Diesel 2,000	STI-P3 None	Copper Double-Walled/Non-Corro	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Community Conservation Association PO Box 459 Bozeman MT 59772 Phone: (406) 587-5667

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3410934	Community Conservation Association		Emigrant	59027	(406) 587-5667

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	4684	4/18/1990 16 / No	Diesel 12,000	STI-P3 None	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: B Bunk Inc 3333 Regent Park Walk Virginia Beach VA 23452 Phone: (757) 498-2438

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3410959	B Bunk Inc	PO Box 519	Emigrant	59027	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	415	4/18/1990 16 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled/Non-Corro	Safe Suction	<div style="display: flex; justify-content: space-between; padding: 2px;"> (A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Marks Ark Inc PO Box 1626 Emigrant MT 59027 Phone: (406) 333-4707

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3410960	Marks Ark Inc	PO Box 1626	Emigrant	59027	(406) 333-4707

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently in Use	1579	4/11/1990 16 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Lifesavers Inc Dorothy Whitehead PO Box 56 Emigrant MT 59027 Phone: (406) 333-4243

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3410965	Lifesavers Inc	PO Box 56	Emigrant	59027	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	4499	4/1/1990 16 / No	Diesel 12,000	STI-P3 None	Galvanized Steel Double-Walled/Non-Corro	Pressurized	<div style="display: flex; flex-wrap: wrap; padding: 2px;"> <div style="margin: 2px;">A B C D E F G H I J K L</div> <div style="margin: 2px;">B D E F G H I J K L</div> </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Craig Newhouse 5 Middlesex Ave Ste 20A Wilmington MA 01887 Phone: (406) 658-7675

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3410978	Tract S7 E1	Evening Star Dr	Emigrant	59027	(978) 658-7675

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 02 Currently in Use	4754	4/23/1990 16 / No	Diesel 10,000	STI-P3 None	No Piping None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	No Yes Yes Yes
2 / 01 Temporarily Out of Use	4753	4/23/1990 16 / No	Diesel 12,000	STI-P3 None	Flexible Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Capstone Project 14449 N 99th St Scottsdale AZ 85260 Phone: (480) 657-2564

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3410989	Capstone Shelter		Emigrant	59027	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Temporarily Out of Use	4827	4/13/1990 16 / No	Diesel 12,000	STI-P3 Double-Walled	Bare Steel Double-Walled/Non-Corro	Pressurized	<div style="display: flex; justify-content: space-between; padding: 2px;"> (A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Helmet of Salvation Shelter Assoc 65 Arcturus Dr PO Box 419 Emigrant MT 59027 Phone: (406) 333-4669

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3413180	Helmet of Salvation Shelter UST	65 Arcturus Dr	Emigrant	59027	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 02 Currently in Use	3123	12/1/1995 10 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Safe Suction	<div style="display: flex; flex-wrap: wrap; padding: 2px;"> <div style="border: 1px solid black; padding: 2px; margin: 2px;">A</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">B</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">C</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">D</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">E</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">F</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">G</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">H</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">I</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">J</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">K</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">L</div> </div>	Yes
							<div style="display: flex; flex-wrap: wrap; padding: 2px;"> <div style="border: 1px solid black; padding: 2px; margin: 2px;">B</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">D</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">E</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">F</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">G</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">H</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">I</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">J</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">K</div> <div style="border: 1px solid black; padding: 2px; margin: 2px;">L</div> </div>	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Gardiner Town Club Inc PO Box 990 Gardiner MT 59030 Phone: (406) 848-7501

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3402285	Town Station	220 Park St	Gardiner	59030	(406) 848-7501

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	3910	4/29/1976 30 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	3911	4/29/1976 30 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently In Use	3912	4/29/1976 30 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently In Use	4247	1/1/2001 05 / No	Diesel 10,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Church Universal & Triumphant Inc PO Box 5000 Gardiner MT 59030 Phone: (406) 848-9242

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3403402	Ranch Office	558 Yellowstone Trl	Gardiner	59030	

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
7 / 07 Currently in Use	1861	10/21/1988 17 / No	Gasoline 20,000	STI-P3 Excavation Liner	Bare Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td></td><td>F</td><td>G</td><td></td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td></td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C			F	G		I	J	K	L	B		E	F	G	H	I		K	L			Yes Yes Yes Yes
A	B	C			F	G		I	J	K	L																					
B		E	F	G	H	I		K	L																							
8 / 08 Currently in Use	1862	10/21/1988 17 / No	Diesel 20,000	STI-P3 Excavation Liner	Bare Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td></td><td>F</td><td>G</td><td></td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td></td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C			F	G		I	J	K	L	B		E	F	G	H	I		K	L			Yes Yes Yes Yes
A	B	C			F	G		I	J	K	L																					
B		E	F	G	H	I		K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Gardiner Conoco PO Box 1063 Gardiner MT 59030 Phone: (406) 848-7742

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3404365	Gardiner Conoco	2nd St & W Stone St	Gardiner	59030	(406) 848-7681

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01	4800	4/8/1977	Gasoline	Asphalt Coated or Bare Steel	Galvanized Steel	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
Temporarily Out of Use		29 / No	10,000	Impressed Current	Impressed Current			Yes Yes Yes																								
2 / 02	4801	4/8/1977	Gasoline	Asphalt Coated or Bare Steel	Galvanized Steel	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
Temporarily Out of Use		29 / No	8,000	Impressed Current	Impressed Current			Yes Yes Yes																								

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Kremer Brothers, Inc PO Box 507 Gardiner MT 59030 Phone: (406) 848-7742

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3406531	Kremers Cenex	401 Scott St W PO Box 507	Gardiner	59030	(406) 848-7742

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C																								
1 / 01 Currently in Use	3189	4/16/1984 22 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
2 / 02 Currently in Use	3190	4/16/1984 22 / No	Gasoline 4,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
3 / 03 Currently in Use	3191	4/16/1984 22 / No	Diesel 4,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
4 / 04 Currently in Use	3192	4/16/1984 22 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: AMFAC Parks & Resorts PO Box 587 Yellowstone Natl Park WY 82190 Phone: (307) 344-5342

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3408868	Gardiner Service Center AMFAC	US Highway 89 S	Gardiner	59030	

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
6 / 06 Currently in Use	3492	4/1/1996 10 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		D	E	F	<input checked="" type="radio"/>	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="radio"/>	H	I	<input checked="" type="radio"/>	K	L																					
7 / 07 Currently in Use	3493	4/1/1996 10 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		D	E	F	<input checked="" type="radio"/>	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="radio"/>	H	I	<input checked="" type="radio"/>	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: AMFAC Parks & Resorts PO Box 587 Yellowstone Natl Park WY 82190 Phone: (307) 344-5342

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3408873	Gardiner Laundry AMFAC	E Park St	Gardiner	59030	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 02 Currently In Use	3494	11/1/1997 08 / No	Diesel 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div style="display: flex; justify-content: space-between; padding: 2px;"> (A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Gardiner Public Schools District 7 & 4 510 Stone St Gardiner MT 59030 Phone: (406) 848-7563

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3409287	Gardiner School Dist 4	510 Stone St	Gardiner	59030	(406) 848-7563

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / S2 Currently in Use	4451	4/24/1987 19 / No	Heating Oil 8,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Yellowstone Park Service Station PO Box 168 Yellowstone Natl Park WY 82190 Phone: (307) 344-2333

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3410929	North Entrance Bldg 101		Gardiner	59030	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / S2 Currently in Use	1744	6/13/1995 11 / No	Heating Oil 550	STI-P3 Double-Walled	Copper Double-Walled/Non-Corro	Safe Suction	<div style="display: flex; justify-content: space-between; padding: 2px;"> (A) (B) (C) (D) (E) (F) (●) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B) (D) (E) (F) (G) (H) (I) (●) (K) (L) </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Yellowstone Park Service Station PO Box 168 Yellowstone Natl Park WY 82190 Phone: (307) 344-2333

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614068	Building HS 2011 South End		Gardiner	59030	(307) 344-2306

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	0	3/31/2004 02 / No	Other 15,000	Fiberglass Reinforced Plastic None	Galvanized Steel None	Pressurized	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> (A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; font-size: 0.8em;"> (B) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div>	Yes Yes Yes No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Mini Mart Inc 442 Keeler Pkwy Pueblo CO 81001 Phone: (719) 948-3071

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3403917	Mini Mart 726	721 W Park St	Livingston	59047	(406) 222-6081

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 13 Currently in Use	1643	3/25/1983 23 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 14 Currently in Use	1644	3/25/1983 23 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 31 Currently in Use	1645	3/25/1983 23 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Gasparra Enterprises LLC PO Box 449 Livingston MT 59047 Phone: (845) 635-1150

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3408071	Sariskys Corner Store	1019 W Park St	Livingston	59047	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Temporarily Out of Use	3031	10/1/1975 30 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
2 / 02 Temporarily Out of Use	3032	10/1/1975 30 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3408713	Town Pump Inc Livingston 2	29 N H St	Livingston	59047	

TankID/Alt TankID	Tag	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status	Numbe	Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Over/C																								
1 / 05 Currently in Use	2577	9/1/1996 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
2 / 06 Currently in Use	2578	9/1/1996 09 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
5 / 03 Currently in Use	2575	9/1/1996 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
6 / 04 Currently in Use	2576	9/1/1996 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Qwest Communications 1600 7th Ave Room 2206 Seattle WA 98191 Phone: (206) 346-7532

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3408777	Qwest Livingston Central Office	302 W Callender St	Livingston	59047	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / S1 Currently In Use	4811	4/15/1957 49 / Ye	Diesel 275	Concrete Double-Walled	Flexible Plastic None	U.S. Suction	<div style="display: flex; flex-wrap: wrap; padding: 2px;"> <div style="margin: 2px;">A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div style="margin: 2px;">B D E F G H I <input checked="" type="radio"/> K L</div> </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Talgo LRC LLC 704 E Gallatin PO Box 992 Livingston MT 59047 Phone: (406) 222-4200

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3409286	Livingston Rebuild Fitness Center	704 E Gallatin St PO Box 992	Livingston	59047	(406) 222-4200

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 02 Currently In Use	4169	2/1/2000 06 / No	Used Oil 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Dead Rock Investments LLC PO Box 1201 Bozeman MT 59771 Phone: (406) 587-0702

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3409906	J & L Country Store	5292 US Highway 89 S	Livingston	59047	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently In Use	2033	5/1/1998 08 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently In Use	2034	5/1/1998 08 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently In Use	2035	5/1/1998 08 / No	Diesel 8,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Livingston Community Hospital Association 504 S 13th St Livingston MT 59047 Phone: (406) 222-3541

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3409965	Livingston Community Hospital	504 S 13th St	Livingston	59047	(406) 222-3541

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / S1 Currently in Use	1550	1/4/1990 16 / No	Heating Oil 2,500	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B D <input checked="" type="radio"/> F G H I J K L</div> </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Park County Shop 414 E Callender St PO Box 1212 Livingston MT 59047 Phone: (406) 222-4106

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3410573	City County Complex	414 E Callender St	Livingston	59047	(406) 222-4106

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 02 Currently in Use	1783	11/1/1995 10 / No	Diesel 3,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Yellowstone Truck Stop 1226 US Highway 10 W Livingston MT 59047 Phone: (406) 222-2131

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3411200	Yellowstone Truck Stop Livingston	1226 US Highway 10 W	Livingston	59047	(406) 222-6180

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	2313	1/1/1989 17 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	2314	1/1/1989 17 / No	Diesel 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	2315	1/1/1989 17 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	2316	1/1/1989 17 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3411741	Kum and Go Store 830	101 Centennial Dr	Livingston	59047	(406) 222-7371

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	562	9/1/1990 15 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	563	9/1/1990 15 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	564	9/1/1990 15 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3413409	Town Pump Inc Livingston 3	2200 Park St S	Livingston	59047	(406) 222-5527

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	2579	5/20/1994 12 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	<input checked="" type="radio"/>	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
<input checked="" type="radio"/>	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
2 / 02 Currently in Use	2580	5/20/1994 12 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	<input checked="" type="radio"/>	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
<input checked="" type="radio"/>	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
3 / 03 Currently in Use	2581	5/1/1994 12 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	<input checked="" type="radio"/>	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
<input checked="" type="radio"/>	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
4 / 04 Currently in Use	2582	5/1/1994 12 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	<input checked="" type="radio"/>	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
<input checked="" type="radio"/>	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
5 / 05 Currently in Use	2583	5/1/1994 12 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	<input checked="" type="radio"/>	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
<input checked="" type="radio"/>	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
6 / 06 Currently In Use	4377	10/1/2001 04 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
7 / 07 Currently In Use	4378	10/1/2001 04 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
8 / 08 Currently In Use	4379	10/1/2001 04 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: TJs Gas N Convenience 204 E Park St Livingston MT 59047 Phone: (406) 222-9720

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3413736	TJs Gas N Convenience	204 W Park St	Livingston	59047	(406) 222-9720

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3371	5/1/1996 10 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	3372	5/1/1996 10 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: D M Curtin Family Limited Partnership 3725 N Oak Trfy Kansas City MO 64116 Phone: (918) 786-5351

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614035	Dennis Curtin	325 Majestic Meadows	Livingston	59047	(406) 333-4056

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4435	10/15/2001 04 / No	Diesel 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Bank of the Rockies NA 205 West Main White Sulphur Springs MT 59645 Phone: (406) 547-3331

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614052	S B Smileys Inc	1306 E Park St	Livingston	59047	(406) 222-2525

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Temporarily Out of Use	4728	9/30/2002 03 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Temporarily Out of Use	4729	9/30/2002 03 / No	Gasoline 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Temporarily Out of Use	4730	9/30/2002 03 / No	Diesel 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Park

Owner Name and Address: Park Farmers Coop PO Box 129 Wilsall MT 59086 Phone: (406) 578-2543

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3406686	Park Farmers Coop	US Highway 89 N	Wilsall	59086	(406) 578-2543

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
13 / 13 Currently in Use	1784	7/1/1993 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> F G H I J K L</div> </div>	Yes Yes Yes Yes
14 / 14 Currently in Use	1785	7/1/1993 13 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> F G H I J K L</div> </div>	Yes Yes Yes Yes
15 / 15 Currently in Use	1786	7/1/1993 13 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
16 / 16 Currently in Use	1787	7/1/1993 13 / No	Heating Oil 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed